

### Building Information

Address: No address 1	PIN: 21-11-218-001	Plan: Rectangular	Stories: 2
Original Owner:		Roof Type: Flat	
Building Names: Marquette School		Foundation:	
Important Dates: ca 1955		Walls: BRICK	
Architect / Builder:		Sheathing:	
Architectural Style: Modern Movement: Modern, General		Windows: Plate Glass, Awning-Style	
		Doors: METAL, GLASS	
Historic Function: EDUCATION: school		Trim: METAL	
Current Function: EDUCATION: school		Roofing:	
References:		Flashing:	
		Chimney:	

### Significance and Potential Eligibility

Class: Building	Condition: Good	Integrity: High	
Yes	1. Heritage value	<b>Individual Eligibility</b>	
No	2. Events (A)	Scope: Local	
No	3. Persons (B)	NHL: No Individual No NR:	
No	4. Architect (C)	<b>District Eligibility</b>	
No	5. Design Elements (C)	District Name:	
Yes	6. Architectural Style (C)	Ottawa Commercial Historic District	
No	7. Archaeology (D)	Contributing: Yes	
No	8. Utilitarian Structure	NR Criteria Considerations:	
Yes	9. Sense of Place	N/A	



Photo ID: 188

### Description and Comments

Good example of the International Style presenting many of the style's common elements: ribbon windows prominent glass entryways, and contrasting brick emphasize the horizontal and vertical features on different portions of the north façade.

### Building Information

Address: 1111 LaSalle Street      PIN: 21-11-217-014  
 Original Owner:  
 Building Names: Ottawa Funeral Home  
 Important Dates: ca 1970  
 Architect / Builder:  
 Architectural Style: Modern Movement: Modern, General

Plan: Rectangular      Stories: 1  
 Roof Type: Side Gable  
 Foundation:  
 Walls: BRICK  
 Sheathing: STONE  
 Windows: Bay  
 Doors: WOOD, GLASS  
 Trim: SYNTHETICS  
 Roofing: ASPHALT  
 Flashing: SYNTHETICS, METAL  
 Chimney:

Historic Function: FUNERARY: mortuary  
 Current Function: FUNERARY: mortuary  
 References:

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	High
No	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:			
No	6. Architectural Style (C)	Ottawa Commercial Historic District			
No	7. Archaeology (D)	Contributing:	No		
No	8. Utilitarian Structure	NR Criteria Considerations:			
Yes	9. Sense of Place	N/A			



Photo ID: 101

### Description and Comments

Simple single-story brick structure with details reminiscent of the Colonial Revival Style: the suggestion of a classical entrance pavilion with white columns and pediment. White pilasters decorate the secondary (south) Brick façade and colonial treatment may have been added after original construction.

### Building Information

Address: 1119 LaSalle Street      PIN: 21-11-217-013  
 Original Owner:  
 Building Names: Illinois Office Supply  
 Important Dates: ca 1920  
 Architect / Builder:  
 Architectural Style: Modern Movement: Modern, General

Historic Function: COMMERCE: business  
 Current Function: COMMERCE: business  
 References: Estimated date from 1925 Sanborn.

Plan: Rectangular      Stories: 1  
 Roof Type: Flat  
 Foundation:  
 Walls:  
 Sheathing: STUCCO  
 Windows: Plate Glass, Hopper  
 Doors: METAL, GLASS  
 Trim:  
 Roofing:  
 Flashing:  
 Chimney:

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	None
No	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope: Local			
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:			
No	6. Architectural Style (C)	Ottawa Commercial Historic District			
No	7. Archaeology (D)	Contributing: No			
No	8. Utilitarian Structure	NR Criteria Considerations:			
No	9. Sense of Place	N/A			



Photo ID: 102

### Description and Comments

Constructed as a print shop, the building is now faced with stucco and brick. Contemporary aluminum windows with lower hopper units are flanked by narrow shutters. Four colonial-style wall lanterns are affixed to the wall.

Stucco, windows and lanterns are all later additions.

### Building Information

Address: 1326 LaSalle Street      PIN: 21-11-217-012  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1945  
 Architect / Builder:  
 Architectural Style: Modern Movement: Modern, General

Historic Function: COMMERCE: business  
 Current Function: COMMERCE: business  
 References: Estimated date based on 1925 and 1949 Sanborn  
 Maps.

Plan: Rectangular      Stories: 1  
 Roof Type: Flat  
 Foundation:  
 Walls: BRICK  
 Sheathing:  
 Windows: Plate Glass  
 Doors: METAL, GLASS  
 Trim: METAL  
 Roofing:  
 Flashing:  
 Chimney:

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	Medium
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope: Local			
No	3. Persons (B)	NHL: No Individual NR: No			
No	4. Architect (C)	<b>District Eligibility</b>			
Yes	5. Design Elements (C)	District Name:			
No	6. Architectural Style (C)	Ottawa Commercial Historic District			
No	7. Archaeology (D)	Contributing: Yes			
No	8. Utilitarian Structure	NR Criteria Considerations:			
Yes	9. Sense of Place	N/A			



Photo ID: 102

### Description and Comments

Single-story building constructed as an auto sales and service building of brown brick. Decorative courses of brick, 3 soldiers alternating with three stacked stretchers, suggest a cornice. Windows and doors have been replaced but the original profiles and penetrations have been retained.

## Building Information

Address:	No address 4	PIN:	Plan:	Rectangular	Stories:	1.5
Original Owner:			Roof Type:	Front Gable		
Building Names:	First State Bank		Foundation:			
Important Dates:	ca 1990		Walls:	BRICK		
Architect / Builder:			Sheathing:			
Architectural Style:	Other: See Comments		Windows:	Plate Glass		
Historic Function:	COMMERCE: business		Doors:	METAL, GLASS		
Current Function:	COMMERCE: business		Trim:	METAL		
References:			Roofing:	ASPHALT		
			Flashing:			
			Chimney:			

## Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	High
No	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:			
No	3. Persons (B)	NHL:	No	Individual	No
				NR:	
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:			
No	6. Architectural Style (C)	Ottawa Commercial Historic District			
No	7. Archaeology (D)	Contributing: No			
No	8. Utilitarian Structure	NR Criteria Considerations:			
No	9. Sense of Place	N/A			



Photo ID: 189

## Description and Comments

Contemporary rectangular bank building of brick, stucco and glass with prominent cross-gable roof. The majority of the curtain wall on the main (west) façade is glass. Central entryway and cornice above are slightly curved.

Building too new to be contributing.

### Building Information

Address: 1201 LaSalle Street      PIN: 21-11-209-010  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1885  
 Architect / Builder:  
 Architectural Style: Late Victorian: Italianate

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Estimated date based on 1883 and 1888 Sanborn  
 Maps.

Plan: Rectangular      Stories: 2  
 Roof Type: Hip  
 Foundation: CONCRETE, CMUs  
 Walls: WOOD  
 Sheathing: METAL  
 Windows: Plate Glass, Double-Hung  
 Doors: WOOD  
 Trim:  
 Roofing: ASPHALT  
 Flashing: METAL  
 Chimney: BRICK

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	Medium
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:			
Yes	6. Architectural Style (C)	Ottawa Commercial Historic District			
No	7. Archaeology (D)	Contributing:	Yes		
No	8. Utilitarian Structure	NR Criteria Considerations:			
Yes	9. Sense of Place	N/A			



Photo ID: 103

### Description and Comments

Late 19th-century Italianate domestic structure retains its original massing, window penetrations and roofline. An enclosed porch stretches across the five-bay main façade; the secondary façade presents two window bays.

Porch enlarged after 1913 and enclosed after 1949.

### Building Information

Address: 1203 LaSalle Street      PIN: 21-11-209-011  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1885  
 Architect / Builder:  
 Architectural Style: Other

Historic Function: COMMERCE: business  
 Current Function: COMMERCE: business  
 References: Estimated date based on 1883 and 1888 Sanborn  
 Maps.

Plan: Rectangular      Stories: 2  
 Roof Type: Front Gable  
 Foundation:  
 Walls: WOOD  
 Sheathing: METAL  
 Windows: Plate Glass, Double-Hung  
 Doors: METAL, GLASS  
 Trim: METAL  
 Roofing: ASPHALT  
 Flashing: METAL  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building    Condition: Good    Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>	
No	2. Events (A)	Scope: Local	
No	3. Persons (B)	NHL: No Individual	Yes
		NR:	
No	4. Architect (C)	<b>District Eligibility</b>	
No	5. Design Elements (C)	District Name:	
No	6. Architectural Style (C)	Ottawa Commercial Historic District	
No	7. Archaeology (D)	Contributing: Yes	
No	8. Utilitarian Structure	NR Criteria Considerations:	
Yes	9. Sense of Place	N/A	



Photo ID: 103

### Description and Comments

Commercial structure with living space above retains its original function. First floor plate glass storefront with central entrance stretches across the entire façade. The second floor, sheathed in aluminum siding, presents three closely-spaced window penetrations. The front-gabled roof may have been a later addition.

Application of aluminum siding and shutters is reversible.

The building was being used as a grocery in 1888. Although the gable roof may not be original, the building's massing, window penetrations, and storefront help maintain sufficient integrity for a contributing structure.

### Building Information

Address: 1205-1207 LaSalle Street PIN: 21-11-209-009  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Late Victorian: Italianate

Historic Function: DOMESTIC: multiple dwelling  
 Current Function: DOMESTIC: multiple dwelling  
 References: Estimated date based on 1875 and 1883 Sanborn  
 Maps.

Plan: Rectangular Stories: 2  
 Roof Type: Hip  
 Foundation:  
 Walls: WOOD  
 Sheathing: METAL, STONE  
 Windows: Double-Hung  
 Doors: WOOD, GLASS  
 Trim:  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class:	Building	Condition:	Fair	Integrity:	Medium
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:	Ottawa Commercial Historic District		
Yes	6. Architectural Style (C)	Contributing:	Yes		
No	7. Archaeology (D)	NR Criteria Considerations:	N/A		
No	8. Utilitarian Structure				
Yes	9. Sense of Place				



Photo ID: 103

### Description and Comments

Late-Victorian duplex residential building with central entries and shared porch roof. The main façade presents six bays. Walls have been sheathed with aluminum and faux stone. Windows have been replaced, using original penetrations, but entry doors appear to be original. The porch hood appears to be original, including the decorative scrollwork above the double entryway. The building's original massing, window penetrations, and roofline all appear to be in place.

Application of aluminum siding and shutters is reversible. Two window penetrations on second floor appear to have been covered.

Behind the primary building is a non-contributing outbuilding.



### Building Information

Address: 1215 LaSalle Street      PIN: 21-11-209-002  
 Original Owner:  
 Building Names: Sands Motel  
 Important Dates: ca 1950  
 Architect / Builder:  
 Architectural Style: Modern Movement: Modern, General

Plan: L      Stories: 2  
 Roof Type: Side Gable  
 Foundation:  
 Walls: WOOD, BRICK  
 Sheathing: WOOD, STONE, BRICK  
 Windows: Plate Glass, Awning-Style  
 Doors: WOOD  
 Trim: METAL, WOOD  
 Roofing: ASPHALT  
 Flashing:  
 Chimney:

Historic Function: DOMESTIC: hotel  
 Current Function: DOMESTIC: hotel  
 References:

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	High
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
Yes	5. Design Elements (C)	District Name:	Ottawa Commercial Historic District		
Yes	6. Architectural Style (C)	Contributing:	Yes		
No	7. Archaeology (D)	NR Criteria Considerations:	N/A		
No	8. Utilitarian Structure				
Yes	9. Sense of Place				



Photo ID: 105-1

### Description and Comments

Mid-century modern two-story motel. Main entrance includes a porte-cochère at the main entrance. Walls are clad with wooden vertical siding, brick and stone. Each room presents a set of four windows next to the door. Second floor walkway presents a simple black metal railing. Gabled roof with angled soffits produces a dynamic visual effect. A very good example of the style. Some wooden siding and the railings have been replaced, but other materials are original. Lower windows were originally awning-style; some windows have been replaced with contemporary double-hung vinyl windows.



Photo ID: 105-2

### Building Information

Address: 1129 Columbus Street      PIN: 21-11-218-004  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1850  
 Architect / Builder:  
 Architectural Style: Mixed

Historic Function: DOMESTIC: single dwelling  
 Current Function: COMMERCE: business  
 References: Sanborn first maps this area in 1888.

Plan: Irregular      Stories: 2  
 Roof Type: Other: Flat and Gable  
 Foundation: CONCRETE  
 Walls: WOOD  
 Sheathing: WOOD, SYNTHETIC  
 Windows: Vinyl Casement, Double-Hung  
 Doors:  
 Trim: SYNTHETICS  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class:	Building	Condition:	Fair	Integrity:	Low
No	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:	Ottawa Commercial Historic District		
No	6. Architectural Style (C)	Contributing:	No		
No	7. Archaeology (D)	NR Criteria Considerations:	N/A		
Yes	9. Sense of Place				



Photo ID: 042

### Description and Comments

Numerous additions, some dating back to the 1880s. The south wing, once a separate storefront, was built prior to 1925 and incorporated into the building after 1950. The one-story east wing facing Superior Street was also built after 1950.

Use of modern materials, replacement windows, etc. leave insufficient character-defining features for this structure to be individually listed. However, the building's massing, including the storefront to the south, has been unchanged since the 1920s.

### Building Information

Address: 1220 Clinton Street      PIN: 21-11-209-001  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1850  
 Architect / Builder:  
 Architectural Style: Other: See Comments

Plan: Rectangular      Stories: 2  
 Roof Type: Front Gable  
 Foundation: CONCRETE, CMUs  
 Walls: WOOD  
 Sheathing: SYNTHETICS  
 Windows: Double-Hung  
 Doors:  
 Trim: SYNTHETICS  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Sanborn first maps this area in 1888.

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	Low
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:			
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:			
No	6. Architectural Style (C)				
No	7. Archaeology (D)	Contributing: No			
No	8. Utilitarian Structure	NR Criteria Considerations:			
Yes	9. Sense of Place	N/A			



Photo ID: 011

### Description and Comments

Although Sanborn maps indicate that this building was standing here in 1888, the extent of changes make it unsuitable for listing, even as a contributing structure.

Vinyl siding and shutters and changes to the window penetrations size and shape obscure the original design of this structure.

### Building Information

Address: West Washington Street PIN:  
 Original Owner:  
 Building Names: St. Columba Church  
 Important Dates: 1882, ca 1910  
 Architect / Builder: Schern & Waugh (Masons), Weiss & Wolf (Carpenters)  
 Architectural Style: Revivals, Late 19th / Early 20th C: Late Gothic Revival  
 Historic Function: RELIGION: religious facility  
 Current Function: RELIGION: religious facility  
 References: Date from corner stone. Veneer added by dean appointed to the church in 1910 (Sequicentennial, p. 181).

Plan: Rectangular Stories: 3.5  
 Roof Type: Front Gable  
 Foundation: STONE  
 Walls: BRICK  
 Sheathing: OTHER, STONE  
 Windows: Leaded Glass, Awning-Style  
 Doors: WOOD  
 Trim: STONE  
 Roofing:  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	High
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	Yes
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
Yes	5. Design Elements (C)	District Name:	Ottawa Commercial Historic District		
Yes	6. Architectural Style (C)	Contributing:	Yes		
No	7. Archaeology (D)	NR Criteria Considerations:	a. Religious property		
No	8. Utilitarian Structure				
Yes	9. Sense of Place				



Photo ID: 213-1

### Description and Comments

HAARGIS No. 304955

Late 19th-century Gothic Revival church of brick with stone foundation. Windows and entries marked by Gothic arches typical of the style. Bell tower rises with corner buttresses at the right of the main entry to a cross-shaped gable roof surmounted by a tall steeple. The building was sheathed in stone veneer during the early 20th century, and the bond between the brick and veneer has failed in many places.

Application of stone veneer prior to the 1972 Survey. Veneer matched the foundation stone, and is now in disrepair, revealing original brick in places. This deterioration is evident in the 1972 survey photo.

Adjacent brick rectory constructed ca 1895.



Photo ID: 213-2

### Building Information

Address: 214 West Washington Street	PIN: 21-11-217-011	Plan: Rectangular	Stories: 1
Original Owner:		Roof Type: Gable end	
Building Names:		Foundation: CONCRETE	
Important Dates: ca 1880		Walls: WOOD	
Architect / Builder:		Sheathing: SYNTHETICS	
Architectural Style: Other		Windows: Double-Hung	
		Doors: WOOD, GLASS	
Historic Function: DOMESTIC: single dwelling		Trim:	
Current Function: DOMESTIC: single dwelling		Roofing: ASPHALT	
References: Sanborn first maps this area in 1883.		Flashing:	
		Chimney: BRICK	

### Significance and Potential Eligibility

Class: Building	Condition: Good	Integrity: Low
No 1. Heritage value	<b>Individual Eligibility</b>	
No 2. Events (A)	Scope:	
No 3. Persons (B)	NHL: No	Individual No
	NR:	
No 4. Architect (C)	<b>District Eligibility</b>	
No 5. Design Elements (C)	District Name:	
No 6. Architectural Style (C)	Ottawa Commercial Historic District	
No 7. Archaeology (D)	Contributing: No	
No 8. Utilitarian Structure	NR Criteria Considerations:	
Yes 9. Sense of Place	N/A	



Photo ID: 205

### Description and Comments

Residential frame structure the size of a Victorian “worker’s cottage” has been significantly altered, including vinyl siding, contemporary windows with changes to the original penetrations.

### Building Information

Address: 216 West Washington Street	PIN: 21-11-217-009	Plan: T	Stories: 2
Original Owner:		Roof Type: Front Gable	
Building Names:		Foundation: CONCRETE	
Important Dates: ca 1885		Walls: WOOD	
Architect / Builder:		Sheathing: SYNTHETICS	
Architectural Style: Other		Windows: Double-Hung	
		Doors: WOOD, GLASS	
Historic Function: DOMESTIC: single dwelling		Trim:	
Current Function: DOMESTIC: single dwelling		Roofing: ASPHALT	
References: Estimated date based on 1883 and 1888 Sanborn Maps.		Flashing:	
		Chimney: BRICK	

### Significance and Potential Eligibility

Class: Building	Condition: Good	Integrity: Medium
Yes 1. Heritage value	<b>Individual Eligibility</b>	
No 2. Events (A)	Scope: Local	
No 3. Persons (B)	NHL: No Individual	No
	NR:	
No 4. Architect (C)	<b>District Eligibility</b>	
No 5. Design Elements (C)	District Name:	
No 6. Architectural Style (C)		
No 7. Archaeology (D)	Contributing: No	
No 8. Utilitarian Structure	NR Criteria Considerations:	
Yes 9. Sense of Place	N/A	



Photo ID: 207

### Description and Comments

Residential frame structure the size of a Victorian "worker's cottage" maintains its original massing, window penetrations, and roofline. Massing and maintenance of original window shapes sufficient for a contributing structure.

### Building Information

Address: 218 West Washington Street	PIN: 21-11-217-019	Plan: Rectangular	Stories: 1
Original Owner:		Roof Type: gable	
Building Names:		Foundation: CONCRETE	
Important Dates: ca 1955		Walls: WOOD	
Architect / Builder:		Sheathing: WOOD	
Architectural Style: Modern Movement: Modern, General		Windows: Plate Glass, Hopper Style	
		Doors: WOOD	
Historic Function: DOMESTIC: single dwelling		Trim: WOOD	
Current Function: DOMESTIC: single dwelling		Roofing: ASPHALT	
References:		Flashing: SYNTHETICS	
		Chimney: BRICK	

### Significance and Potential Eligibility

Class: Building	Condition: Excellent	Integrity: High
Yes 1. Heritage value	<b>Individual Eligibility</b>	
No 2. Events (A)	Scope: Local	
No 3. Persons (B)	NHL: No	Individual No
		NR:
No 4. Architect (C)	<b>District Eligibility</b>	
No 5. Design Elements (C)	District Name:	
Yes 6. Architectural Style (C)	Ottawa Commercial Historic District	
No 7. Archaeology (D)	Contributing: No	
No 8. Utilitarian Structure	NR Criteria Considerations:	
Yes 9. Sense of Place	N/A	



Photo ID: 209

### Description and Comments

Mid-century modern frame home. Soffit of gabled roof extends over the main façade and serves as porch roof. Foliate iron supports typical of the period frame the front entry. Window shape delineates the public and private areas of the house: to the left of the entry, a large picture window and group of four smaller windows suggest the living and dining areas. To the right of the entry, a set of ribbon windows suggests bedrooms.

### Building Information

Address: 100-106 West Superior Street	PIN: 21-11-210-016	Plan: Rectangular	Stories: 2
Original Owner:		Roof Type: Flat	
Building Names:		Foundation:	
Important Dates: ca 1950		Walls: BRICK	
Architect / Builder:		Sheathing:	
Architectural Style: Modern Movement: International Style		Windows: Plate Glass, Double-Hung	
		Doors: METAL, GLASS	
Historic Function: COMMERCE: specialty store		Trim: METAL	
Current Function: COMMERCE: specialty store		Roofing:	
References:		Flashing:	
		Chimney:	

### Significance and Potential Eligibility

Class: Building	Condition: Excellent	Integrity: High
Yes 1. Heritage value	<b>Individual Eligibility</b>	
No 2. Events (A)	Scope: Local	
No 3. Persons (B)	NHL: No	Individual No
	NR:	
No 4. Architect (C)	<b>District Eligibility</b>	
Yes 5. Design Elements (C)	District Name:	
Yes 6. Architectural Style (C)	Ottawa Commercial Historic District	
No 7. Archaeology (D)	Contributing: Yes	
No 8. Utilitarian Structure	NR Criteria Considerations:	
Yes 9. Sense of Place	N/A	



Photo ID: 202

### Description and Comments

Two-story commercial structure in the International Style, with wide overhangs supported by cantilevered concrete beams faced in brick. The second-floor walkway extends the same distance as the roof and has simple metal railings. Ribbon-shaped windows on the second floor and plate glass on the first are both characteristic of the style.

Photo ID:

No significant alterations.

Single address includes frame structure next door (106), which has been surveyed as a separate record.



## Building Information

Address: 106 West Superior Street PIN:  
Original Owner:  
Building Names:  
Important Dates: ca 1885  
Architect / Builder:  
Architectural Style: Mid-19th Century: Greek Revival

Historic Function: DOMESTIC: single dwelling  
Current Function: DOMESTIC: single dwelling  
References: Sanborn first maps this area in 1888.

Plan: Rectangular Stories: 1.5  
Roof Type: Front Gable  
Foundation:  
Walls: WOOD  
Sheathing: WOOD  
Windows: Double-Hung, Plate Glass  
Doors: WOOD  
Trim:  
Roofing: ASPHALT  
Flashing:  
Chimney:

## Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual No NR:
No	4. Architect (C)	<b>District Eligibility</b>
Yes	5. Design Elements (C)	District Name:
Yes	6. Architectural Style (C)	Ottawa Commercial Historic District
No	7. Archaeology (D)	Contributing: Yes
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	



Photo ID: 222

## Description and Comments

Good example of a Greek Revival Style home on a small scale. Doric columns support the porch roof, a shallow hip roof resting on a simple entablature. The central entry is offset a bit to accommodate a larger room on the right. A high window to the left of the front door suggests the placement of the stairway to the second floor, which has a single window in the center of the façade, which is framed by soffit returns characteristic of the style.

Vinyl siding obscures original trim on windows and doors.

Original massing and windows profiles provide sufficient integrity for a contributing resource.

### Building Information

Address: 110-112 West Superior Street	PIN: 21-11-210-018	Plan: Rectangular	Stories: 1.5
Original Owner:		Roof Type: Side Gable	
Building Names:		Foundation:	
Important Dates: ca 1920		Walls: BRICK	
Architect / Builder:		Sheathing: SYNTHETICS	
Architectural Style: Revivals, Late 19th / Early 20th C: Tudor Revival		Windows: Double-Hung	
		Doors: WOOD	
Historic Function: DOMESTIC: multiple dwelling		Trim:	
Current Function: DOMESTIC: multiple dwelling		Roofing: ASPHALT	
References: Estimated date based on 1913 and 1925 Sanborn Maps.		Flashing:	
		Chimney: BRICK	

### Significance and Potential Eligibility

Class: Building	Condition: Good	Integrity: High
Yes 1. Heritage value	<b>Individual Eligibility</b>	
No 2. Events (A)	Scope: Local	
No 3. Persons (B)	NHL: No Individual NR:	No
No 4. Architect (C)	<b>District Eligibility</b>	
Yes 5. Design Elements (C)	District Name:	
Yes 6. Architectural Style (C)	Ottawa Commercial Historic District	
No 7. Archaeology (D)	Contributing: Yes	
No 8. Utilitarian Structure	NR Criteria Considerations:	
Yes 9. Sense of Place	N/A	



Photo ID: 203

### Description and Comments

This duplex residential structure of brown brick presents the massing of a building in the Tudor Revival style. Identical entrances are located at each end of the main façade, with small curved hoods over each porch. The massing of the gabled dormers on the second floor in particular suggest the style, though these seem to have been covered in plain clapboard siding sometime after the original construction.

What appears to be vinyl siding on the dormers probably hides Tudor details or decorative wooden siding.

Original massing and windows profiles provide sufficient integrity for a contributing resource.

### Building Information

Address: 109 West Superior Street PIN: 21-11-218-003  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1910  
 Architect / Builder:  
 Architectural Style: American, Late 19th / Early 20th C: Craftsman

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Estimated date based on 1898 and 1913 Sanborn Maps.

Plan: Rectangular Stories: 2.5  
 Roof Type: Hip  
 Foundation: BRICK  
 Walls: WOOD  
 Sheathing: WOOD  
 Windows: Double-Hung, Leaded  
 Doors: WOOD, GLASS  
 Trim: WOOD  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: High

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual Yes NR:
No	4. Architect (C)	<b>District Eligibility</b>
Yes	5. Design Elements (C)	District Name:
Yes	6. Architectural Style (C)	Ottawa Commercial Historic District
No	7. Archaeology (D)	Contributing: Yes
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 192

### Description and Comments

Fine example of a wooden American Foursquare in very good condition. Simple Doric columns and characteristically low railing on front porch suggest that these materials are original. Possible replacement windows on second floor.

Behind the house is a garage, a non-contributing structure of indeterminate age.

### Building Information

Address: 111 West Superior Street PIN: 21-11-218-002  
Original Owner:  
Building Names:  
Important Dates: ca 1950, ca 1980  
Architect / Builder:  
Architectural Style: American, Late 19th / Early 20th C: Commercial Style  
Historic Function: COMMERCE: business  
Current Function: COMMERCE: business  
References: Constructed after publication of the 1949 Sanborn Map.

Plan: Rectangular Stories: 1  
Roof Type: Flat  
Foundation:  
Walls: CONCRETE  
Sheathing: BRICK  
Windows: Plate Glass  
Doors: METAL, GLASS  
Trim:  
Roofing:  
Flashing:  
Chimney:

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Low

No	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual No NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	Ottawa Commercial Historic District
No	7. Archaeology (D)	Contributing: No
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 193

### Description and Comments

Simple rectangular one-story masonry commercial structure has a mansard-type hood of asphalt shingles stretching across the entire building. Storefront has been replaced with red brick fill, a single metal and glass doorway and narrow window.

Storefront replaced and hood added after original construction.

### Building Information

Address: 212 West Superior Street PIN: 21-11-209-008  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Late Victorian: Italiante  
  
 Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Sanborn first maps this area in 1883.

Plan: Rectangular Stories: 2  
 Roof Type: Front Gable  
 Foundation:  
 Walls: WOOD  
 Sheathing: SYNTHETICS  
 Windows: Double-Hung, Plate Glass  
 Doors: WOOD, GLASS  
 Trim: SYNTHETICS  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Low  
 No 1. Heritage value **Individual Eligibility**  
 No 2. Events (A) Scope: Local  
 No 3. Persons (B) NHL: No Individual No  
 NR:  
 No 4. Architect (C) **District Eligibility**  
 No 5. Design Elements (C) District Name:  
 No 6. Architectural Style (C) Ottawa Commercial Historic  
 District  
 No 7. Archaeology (D) Contributing: Yes  
 No 8. Utilitarian Structure NR Criteria Considerations:  
 Yes 9. Sense of Place N/A



Photo ID: 194

### Description and Comments

Two-story single-family home of wood, now clad in vinyl with green shutters. Picture window and spindle decoration on curved porch roof appear to be original. The building's original massing, window penetrations, and roofline all appear to be in place, allowing it to serve as a contributing structure.

It is likely some windows openings have been covered on the west façade. Replacement windows appear to have been added at the southeast corner of the building.

Behind the residence is a non-contributing outbuilding of indeterminate age.

### Building Information

Address: 214 West Superior Street PIN: 21-11-209-007  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1890  
 Architect / Builder:  
 Architectural Style: Late Victorian: Italiante

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Estimated date based on 1888 and 1891 Sanborn  
 Maps.

Plan: L Stories: 2  
 Roof Type: Front Gable  
 Foundation:  
 Walls: WOOD  
 Sheathing: METAL  
 Windows: Double-Hung  
 Doors: WOOD  
 Trim:  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual No NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	Ottawa Commercial Historic District
No	7. Archaeology (D)	Contributing: Yes
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID:

### Description and Comments

Simple "L-shaped" gabled frame dwelling with hip-roofed porch at main entrance. The building's original massing, window penetrations and roofline all appear to be in place, allowing it to serve as a contributing structure.

### Building Information

Address: 216 West Superior Street PIN: 21-11-209-006  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Other

Historic Function: COMMERCE: business  
 Current Function: COMMERCE: business  
 References: Sanborn first maps this area in 1888.

Plan: Irregular Stories: 1  
 Roof Type: Front Gable  
 Foundation: CONCRETE  
 Walls: WOOD  
 Sheathing: SYNTHETICS  
 Windows: Double-Hung, Plate Glass  
 Doors: WOOD, GLASS  
 Trim:  
 Roofing:  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope:
No	3. Persons (B)	NHL: No Individual No
		NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	
No	7. Archaeology (D)	Contributing: No
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 197

### Description and Comments

One-story frame home with vinyl siding. The building's original massing, window penetrations and roofline all appear to be in place.

Behind the residence is a non-contributing outbuilding of indeterminate age.

### Building Information

Address: 222 West Superior Street PIN: 21-11-209-005  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Other

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Sanborn first maps this area in 1888.

Plan: Rectangular Stories: 1  
 Roof Type: Front Gable  
 Foundation: OTHER, Rubble  
 Walls: WOOD  
 Sheathing: SYNTHETICS  
 Windows: Double-Hung,  
 Doors:  
 Trim:  
 Roofing:  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual No NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	
No	7. Archaeology (D)	Contributing: No
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 198

### Description and Comments

Single-story frame front-gable residence typical of the period. Shape of windows on east facade suggests 1950's vintage, probably replacement windows. Building also has vinyl shutters.

Behind the residence is an outbuilding of indeterminate age.



### Building Information

Address: 226 West Superior Street    PIN: 21-11-209-004  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Other

Historic Function: COMMERCE: business  
 Current Function: COMMERCE: business  
 References: Sanborn first maps this area in 1888.

Plan: Rectangular    Stories: 2  
 Roof Type: Front Gable  
 Foundation:  
 Walls: WOOD  
 Sheathing:  
 Windows: Double-Hung, Casement  
 Doors:  
 Trim:  
 Roofing:  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building    Condition: Good    Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No    Individual    No NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	
No	7. Archaeology (D)	Contributing: No
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 199

### Description and Comments

Simple gabled frame dwelling with hip-roofed porch at main entrance. The building's original massing, window penetrations and roofline all appear to be in place.

Replacement windows on first floor detract from integrity. Building's massing would allow classification as contributing structure.

Behind the residence is an outbuilding of indeterminate age.

### Building Information

Address: 230 West Superior Street PIN: 21-11-209-003  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Other

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Sanborn first maps this area in 1888.

Plan: Rectangular Stories: 1  
 Roof Type: gable end  
 Foundation:  
 Walls: WOOD  
 Sheathing: SYNTHETICS  
 Windows: Double-Hung  
 Doors:  
 Trim: SYNTHETICS  
 Roofing: ASPHALT  
 Flashing:  
 Chimney: BRICK

### Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Medium

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual No NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	
No	7. Archaeology (D)	Contributing: No
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 200

### Description and Comments

Single-story residential frame structure, likely with later addition of porch. Later porch enclosure and vinyl siding typical of homes in the area. The building retains its original massing, window penetrations, and roofline.

Behind the residence is an outbuilding of indeterminate age.

## Building Information

Address: 215 West Superior Street PIN: 21-11-217-008  
Original Owner:  
Building Names:  
Important Dates: ca 1880  
Architect / Builder:  
Architectural Style: Other

Historic Function: DOMESTIC: single dwelling  
Current Function: DOMESTIC: single dwelling  
References: Sanborn first maps this area in 1883.

Plan: Rectangular Stories: 1  
Roof Type: Hip  
Foundation: CONCRETE  
Walls: WOOD  
Sheathing: METAL  
Windows: Double-Hung, Replacements  
Doors: SYNTHETICS  
Trim:  
Roofing:  
Flashing:  
Chimney: BRICK

## Significance and Potential Eligibility

Class: Building Condition: Good Integrity: Low

Yes	1. Heritage value	<b>Individual Eligibility</b>
No	2. Events (A)	Scope: Local
No	3. Persons (B)	NHL: No Individual No NR:
No	4. Architect (C)	<b>District Eligibility</b>
No	5. Design Elements (C)	District Name:
No	6. Architectural Style (C)	
No	7. Archaeology (D)	Contributing:
No	8. Utilitarian Structure	NR Criteria Considerations:
Yes	9. Sense of Place	N/A



Photo ID: 196

## Description and Comments

One-story frame home with asymmetrical three-bay façade, with windows and entryway on main façade possibly replaced in the 1920s. Porch of CMUs and concrete stretches the full length of the main façade, and has a canopy of wood and asphalt shingles supported by mid-20th-century metal supports. The building's original massing and roofline appear to be in place. Window penetrations on the east façade retain their original proportions.

The windows and door on main façade could be as late as the 1920s. Metal siding, new windows, new porch of CMUs with metal foliate railings and supports common in the 1960s and later.

Behind the residence is an outbuilding of indeterminate age.

### Building Information

Address: 300 West Superior Street PIN: 21-11-208-005  
 Original Owner:  
 Building Names:  
 Important Dates: ca 1880  
 Architect / Builder:  
 Architectural Style: Other

Plan: Rectangular Stories: 2  
 Roof Type: Front gable  
 Foundation: CONCRETE  
 Walls: BRICK  
 Sheathing: SYNTHETICS  
 Windows: Double-Hung  
 Doors:  
 Trim:  
 Roofing:  
 Flashing:  
 Chimney: BRICK

Historic Function: DOMESTIC: single dwelling  
 Current Function: DOMESTIC: single dwelling  
 References: Sanborn first maps this area in 1888.

### Significance and Potential Eligibility

Class:	Building	Condition:	Good	Integrity:	Medium
Yes	1. Heritage value	<b>Individual Eligibility</b>			
No	2. Events (A)	Scope:	Local		
No	3. Persons (B)	NHL:	No	Individual	No
		NR:			
No	4. Architect (C)	<b>District Eligibility</b>			
No	5. Design Elements (C)	District Name:			
No	6. Architectural Style (C)				
No	7. Archaeology (D)	Contributing:	No		
No	8. Utilitarian Structure	NR Criteria Considerations:	N/A		
Yes	9. Sense of Place				



Photo ID: 201

### Description and Comments

Two-story frame front-gable residence typical of the period. Later porch enclosure and vinyl siding typical of homes in the area. The building's massing, window penetrations, and roofline are unchanged.

Behind the residence is an outbuilding of indeterminate age.